Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

 1125
 3802 POPLAR AVE -SEAGATE
 NY Spills
 S102560173

 West
 3802 POPLAR AVE
 N/A

West 3802 POPLAR AVE > 1 BROOKLYN, NY

1.471 mi. 7767 ft.

 Relative:
 SPILLS:

 Higher
 Name:

 3802 POPLAR AVE -SEAGATE

 Actual:
 Address:
 3802 POPLAR AVE

 0 ft.
 City,State,Zip:
 BROOKLYN, NY

Spill Number/Closed Date: 9612541 / 2001-05-01

 Facility ID:
 9612541

 Facility Type:
 ER

 DER Facility ID:
 215309

 Site ID:
 264166

 DEC Region:
 2

Spill Cause: Unknown Spill Class: C₁ SWIS: 2401 1997-01-22 Spill Date: Investigator: **CESAWYER** Referred To: Not reported Reported to Dept: 1997-01-22 CID: 195

Water Affected: Not reported Private Dwelling Spill Source: Spill Notifier: Local Agency Cleanup Ceased: Not reported Cleanup Meets Std: False 1997-01-23 Last Inspection: Recommended Penalty: False **UST Trust:** False Remediation Phase:

Date Entered In Computer: 1997-01-22
Spill Record Last Update: 2004-01-30
Spiller Name: GABE ROSNER
Spiller Company: COUNTY OIL
Spiller Address: 18-65 42ND STREET

Spiller Company: 001
Contact Name: MR. WEISS

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

TANK OVERFILL IN BACK, MIDDLE PORTION OF BUILDING, JUST BENEATH TERRACE. OCCUPANTS COMPLAINING OF OIL ODORS. INTERVIEWED SUPER, MR. LEONID ALEYNIKOV (718) 996-3316, WHO STATED THAT THE DELIVERY DRIVER WAS ASLEEP IN THE TRUCK DURING THE DELIVERY AND CAUSED OVERFILL. SPOKE TO MR. WEISS, 1371 CONEY ISLAND AVENUE, CONEY ISLAND, NEW YORK 11230, (718) 376-1309, THE BUILDING MANAGER WHO STATED THAT THE OIL COMPANY WAS COUNTY OIL. AND HE WAS SPEAKING WITH SOPHIA. OIL COMPANY CAME AND PUT SPEEDI DRY DOWN, BUT CONTAMINATED SOIL IS PRESENT JUST UNDER WINDOWS. INSPECTED THE BASEMENT AND LOCATED ONE (1) THREE THOUSAND (3,000) GALLON SINGLE WALL STEEL AST WITH CONCRETE WALL AS SECONDARY CONTAINMENT AND DIRT FLOOR. EVIDENCE OF GASKET LEAKING ON TANK MANWAY, WHCIH WAS REPAIRED. TANK HAS NO HIGH LEVEL ALARM OR OVERFILL PROTECTION. REGISTRATION STILL UNKNOWN. 1/24/97 CALLED COUNTY OIL AND SPOKE TO DAVID ROASNER AND INFORMED HIM THAT HE WAS RESPONSIBLE AS THE OIL COMPANY TO CLEAN UP THE SPILL. HE ARGUED WITH ME OVER MATTER, STATING THAT HE SUBCONTRACTED ANOTHER COMPANY. I TOLD

SAWYER 1/23/97 mmm:INSPECTED PROPERTY AND LOCATED OIL SPILL DUE TO

HIM THAT HE WAS STILL RESPONSIBLE, AND FAILED TO MAKE PROPER

NOTIFICATIONS, AND FAILED TO DO PROPER CLEANUP. HE SAID HE WOULD GET

Map ID MAP FINDINGS

Direction Distance Elevation

Site Database(s) EPA ID Number

BACK TO ME. LATER HE LEFT MESSAGE ON MACHINE STATING THAT HE WOULD HAVE CREW THERE TODAY TO DIG OUT CONTMAINATED SOIL, AND HAVE THEM THERE AGAIN TOMORROW IF NEEDED. 1/27/97:CALL FROM JOHN MOSHER (718) 449-5408 WHO STATED THAT HE LIVES IN THE APRATMENT JUST TO THE JUST TO LEFT OF SPILL. STATES THAT HIS APARTMENT AND HALLWAY HAVE TERRIBLE OIL ODOR AND THAT ODORS ARE GETTING WORSE. CALLED UP OIL COMPANY TO ARRANGE FOR SITE INSPECTION. SPILL # CLOSED OUT WITH 05/01/01 DATE PER ALBANY'S MAY 2001 MONTHLY REPORT. 3/19/02-Vought-Spill

EDR ID Number

PER ALBANY'S MAY 2001 MONTHLY REPORT. 3/19/02-Vought-Spitransferred from Mulqueen to Vought. 1/5/04-Vought-Spill transferred from Vought to Austin. 01/27/04 - Sawyer - Spill transferred from

Austin to Sawyer. "

"SPILL IS IN REAR OF RESIDENCE - ORIGINAL COMPLAINT FROM CITIZEN FOR

NOXIOUS ODOR - INVESTIGATION REVEALED FUEL OIL ON GROUND - ONE

OCCUPANT HAD TO LEAVE RESIDENSE DUE TO FUMES."

All Materials:

Remarks:

Site ID: 264166 1040369 Operable Unit ID: Operable Unit: 01 Material ID: 341183 Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: .00 Units: G Recovered: .00

Oxygenate: Not reported